

Hazel Avenue Infrastructure Project

Tree Impact Inventory



Tree	Address	Size	Species	Condition	Notes
1	1540 Hazel				Previously removed
2	1502 Hazel	35	Silver Maple	3	Storm sewer work in conflict. Multiple leaders, suckering, minor deadwood, weak crotches
3	1450 Hazel	12	Silver Maple	3/4	Storm sewer work and condition Trunk scar, weak crotch, decay multiple leaders, minor deadwood, fork at 3'
4	978 Maple Ct	26	Siberian Elm	3	Storm sewer work weak crotch, one-sided, multiple leaders, slight sweep, minor deadwood
5	978 Maple Ct	15	Norway Maple	3	Sidewalk work slight lean, weak crotch, multiple leaders, broken branches
6	1414 Hazel	32	Silver Maple	3	Sidewalk and power lines work Multiple leaders, suckering, minor deadwood, overhead wires
9	1344 Hazel	19	Siberian Elm	3	Sidewalk and power lines work Multiple leaders, suckering, minor deadwood, overhead wires
8		12	Mulberry		Previously removed
7		20	Mulberry		Previously removed
10	963 Cedar St	11	Norway Maple	3	Sidewalk work? twist in trunk, pruned for side wires, one sided
11A	963 Cedar St	14	American Elm	3	Sidewalk work? Sweep, multiple leaders, pruned for side wires, minor deadwood, suckering
11B	963 Cedar St	8	Norway Maple	4	Sidewalk work? damaged leader, pruned for overhead wires, one sided, suckering
12	1315 Hazel	5	Red Maple	3	Sidewalk work Basal scar
13	951 Hemlock	17	Norway Maple	3	Sidewalk work weak crotch, multiple leaders, sucker growth, broken branches
14		18	Norway Maple		Previously removed
15	1007 Prairie	31	Honey locust	2	Sidewalk work weak crotch, multiple leaders, sucker growth
16	1250 Hazel	24	Honey locust	3	Sidewalk work multiple leaders, broken branches, minor deadwood, sucker growth
17A	1005 Stratford	30	Honey locust	3	Sidewalk work weak crotch, multiple leaders, minor deadwood
17B	1216 Hazel	24	Honey locust	3	Sidewalk work weak crotch, multiple leaders, sucker growth, minor deadwood

Tree	Address	Size	Species	Condition	Notes
18	1210 Hazel	25	Honey locust	3	Sidewalk work slight sweep, multiple leaders, sucker growth, minor deadwood
19	1008 Wayne	25	Honey locust	3	Sidewalk work weak crotch, multiple leaders, sucker growth, broken branches
20	1151 Hazel	16	Norway Maple	4	Storm sewer work trunk scar, weak crotch, decay, sucker growth
21	1128 Hazel	16	Honey Locust	3	Storm sewer work? Twist in trunk, suckering, minor deadwood, multiple leaders
22	1048 Hazel	32	Silver Maple	4	Storm sewer work? trunk scar, decay, weak crotch, broken branches, multiple leaders
23	1048 Hazel	23	Silver Maple	3	Storm sewer work? Multiple leaders, suckering, branch scars,
24	1041 Hazel	19	Norway Maple	3	Driveway apron work/realignment girdling root, weak crotch, multiple leaders
25	1038 Hazel	19	Norway Maple	3	Storm sewer work? multiple leaders, sucker growth, girdling root
26	1030 Hazel	32	Siberian Elm	3	Storm sewer work? Lean weak crotch, slight sweep, minor deadwood, multiple leaders


Tree	Address	Size	Species	Condition	Notes
1	1540 Hazel				Previously removed



Tree	Address	Size	Species	Condition	Notes
2	1502 Hazel	35	Silver Maple	3	Storm sewer work in conflict. Multiple leaders, suckering, minor deadwood, weak crotches



Tree	Address	Size	Species	Condition	Notes
3	1450 Hazel	12	Silver Maple	3/4	Storm sewer work and condition Trunk scar, weak crotch, decay multiple leaders, minor deadwood, fork at 3'



Tree	Address	Size	Species	Condition	Notes
4	978 Maple Ct	26	Siberian Elm	3	Storm sewer work weak crotch, one-sided, multiple leaders, slight sweep, minor deadwood



Google


Tree	Address	Size	Species	Condition	Notes
5	978 Maple Ct	15	Norway Maple	3	Sidewalk work slight lean, weak crotch, multiple leaders, broken branches



Tree	Address	Size	Species	Condition	Notes
6	1414 Hazel	32	Silver Maple	3	Sidewalk and power lines work Multiple leaders, suckering, minor deadwood, overhead wires




Tree	Address	Size	Species	Condition	Notes
9	1344 Hazel	19	Siberian Elm	3	Sidewalk and power lines work Multiple leaders, suckering, minor deadwood, overhead wires
8		12	Mulberry		Previously removed
7		20	Mulberry		Previously removed




Tree	Address	Size	Species	Condition	Notes
10	963 Cedar St	11	Norway Maple	3	Sidewalk work? twist in trunk, pruned for side wires, one sided
11A	963 Cedar St	14	American Elm	3	Sidewalk work? Sweep, multiple leaders, pruned for side wires, minor deadwood, suckering
11B	963 Cedar St	8	Norway Maple	4	Sidewalk work? damaged leader, pruned for overhead wires, one sided, suckering



Tree	Address	Size	Species	Condition	Notes
12	1315 Hazel	5	Red Maple	3	Sidewalk work Basal scar




Tree	Address	Size	Species	Condition	Notes
13	951 Hemlock	17	Norway Maple	3	Sidewalk work weak crotch, multiple leaders, sucker growth, broken branches
14		18	Norway Maple		Previously removed



Tree	Address	Size	Species	Condition	Notes
15	1007 Prairie	31	Honey locust	2	Sidewalk work weak crotch, multiple leaders, sucker growth



Tree	Address	Size	Species	Condition	Notes
16	1250 Hazel	24	Honey locust	3	Sidewalk work multiple leaders, broken branches, minor deadwood, sucker growth



Tree	Address	Size	Species	Condition	Notes
17A	1005 Stratford	30	Honey locust	3	Sidewalk work weak crotch, multiple leaders, minor deadwood



Tree	Address	Size	Species	Condition	Notes
17B	1216 Hazel	24	Honey locust	3	Sidewalk work weak crotch, multiple leaders, sucker growth, minor deadwood



Tree	Address	Size	Species	Condition	Notes
18	1210 Hazel	25	Honey locust	3	Sidewalk work slight sweep, multiple leaders, sucker growth, minor deadwood



Tree	Address	Size	Species	Condition	Notes
19	1008 Wayne	25	Honey locust	3	Sidewalk work weak crotch, multiple leaders, sucker growth, broken branches




Tree	Address	Size	Species	Condition	Notes
20	1151 Hazel	16	Norway Maple	4	Storm sewer work trunk scar, weak crotch, decay, sucker growth




Tree	Address	Size	Species	Condition	Notes
21	1128 Hazel	16	Honey Locust	3	Storm sewer work? Twist in trunk, suckering, minor deadwood, multiple leaders



Tree	Address	Size	Species	Condition	Notes
22	1048 Hazel	32	Silver Maple	4	Storm sewer work? trunk scar, decay, weak crotch, broken branches, multiple leaders



Tree	Address	Size	Species	Condition	Notes
23	1048 Hazel	23	Silver Maple	3	Storm sewer work? Multiple leaders, suckering, branch scars,



Tree	Address	Size	Species	Condition	Notes
24	1041 Hazel	19	Norway Maple	3	Driveway apron work/realignment girdling root, weak crotch, multiple leaders



Tree	Address	Size	Species	Condition	Notes
25	1038 Hazel	19	Norway Maple	3	Storm sewer work? multiple leaders, sucker growth, girdling root



Tree	Address	Size	Species	Condition	Notes
26	1030 Hazel	32	Siberian Elm	3	Storm sewer work? Lean weak crotch, slight sweep, minor deadwood, multiple leaders

